

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	22	(weld near (electrode or wire)) and ((steel or iron or fe or ferrous or ferric) near (sheath or coating or layer or outer))	USOCR	OR	ON	2005/10/07 09:27
L2	22	l1 and ((al sub "2" O sub "3") or (na sub "2" O sub "3") or (mgco sub "3") or (mgal) or (caf sub "2") or (mgo))	USOCR	OR	ON	2005/10/07 09:28
L3	14	l2 and core	USOCR	OR	ON	2005/10/07 09:25
L4	364	(weld near (electrode or wire)) and ((steel or iron or fe or ferrous or ferric) near (sheath or coating or layer or outer))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:27
L5	363	l4 and ((al sub "2" O sub "3") or (na sub "2" O sub "3") or (mgco sub "3") or (mgal) or (caf sub "2") or (mgo))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:47
L6	363	l5 and (al sub "2" O sub "3") and (na sub "2" O sub "3")	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:29
L7	232	l6 and core	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:29
L8	121	l7 and (arc near welding)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:48
L9	10	l7 and (submerged near arc near welding)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:33
L10	78559	l and (fe or (femg) or (fesi))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:34
L11	4	l9 and (fe or (femg) or (fesi))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:47
L12	60	l8 and (fe or (femg) or (fesi))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:35

L13	42	l12 and @ay<="2003"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:48
L14	121891	"219"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:46
L15	69749	l14 and ((al sub "2" O sub "3") or (na sub "2" O sub "3") or (mgco sub "3") or (mgal) or (caf sub "2") or (mgo))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:47
L16	69274	l14 and (((al sub "2" O sub "3") and (na sub "2" O sub "3")) or (mgco sub "3") or (mgal) or (caf sub "2") or (mgo))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:47
L17	1913	l16 and (fe or (femg) or (fesi))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:47
L18	482	l17 and (arc near welding)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:48
L19	474	l18 and @ay<="2003"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:48
L20	17	l19 and ((core or cored) near welding near wire)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/10/07 09:48